
Furnace Demo Over 3,000 lbs. in cast iron




Each weigh 500 lbs.




Empty furnace room



20 year old hot water tank behind furnace







Replaced




Swollen and leaking sewer lines




Dripping on new furnace must be replaced




New furnace and piping



New piping above furnace



Two Furnaces



Crane removes and replace Sanctuary rooftop unit



Old unit scrapped by Don Jones




Gary Dressler leaning on new unit





Pad for new unit in Fellowship Hall




New Pad



Fellowship Hall's new unit




Duct work in Fellowship Hall



Curtain rod need shortened



Shorten curtain rod




Need seamstress




Reduce width of curtain



New retaining walls







To be painted plus top siding repaired



sand/prime/two top coats



Front entrance posts sand/ prime/paint




One post needs replaced



Front door needs paint



Front doors before paint



When we have the lift need to paint light and flag pole and cross



Light post



Flag pole



Flagpole needs paint



Cross



Cross



Support holding cross

