

LUXURY JET AVIATION LLC

2009 Legacy 600- Low Time / Low Cycle/ One Owner/No Damage/ Fresh Interior



David Crowe +1 (760)668-1222 Jetpilots@hotmail.com Eamircraft.com













Airframe Total Time: 2545 Total Landings 1219 Maintenance Tracking Camp

**Engines: AE3007A1E Engine 1 Time 2545 Engine 1 Cycles 1219
Engine 2 Time 2545 Engine 2 Cycles 1219**

Engine Maintenance Program CorporateCare

APU Notes: T-62T-40C14 Total Hours: 2,337

Avionics/Radios

**Dual Honeywell Primus 1000 IFCS/Primus II
F/DIR: Dual Honeywell Primus 1000 IFCS
AUTOPILOT: Honeywell Primus 1000 IFCS
COMMS: Triple Honeywell RCZ-833K w/8.33kHz spacing
DME: Dual Honeywell RNZ-850
TPDR: Dual Honeywell RCZ-833K Mode S
IRS: Dual Honeywell LASEREF IV
FDR: Honeywell FDR
TAWS: Honeywell Mark V EGPWS w/ Windshear & escape guidance**

**EFIS: Honeywell Primus 1000 5-tube 8x7-inch color
FMS: Dual Honeywell NZ-2000 w/GPS
RADAR: Honeywell Primus 880 Mod P w/turbulence & dual controllers
NAVS: Dual Honeywell RNZ-850
ADF: Dual Honeywell RNZ-850
HI FREQ: Dual Honeywell KHF-1053 w/SELCAL
CVR: Honeywell CVR
TCAS: Honeywell TCAS-2000 TCASS-II w/change 7
RDR ALT: Honeywell RT-300**

Additional Equipment

**Wi-Fi High Speed ATG Internet
Entertainment System w/Airshow 4000, dual DVD Players,
Forward and Aft Bulkhead 17-inch LCD Monitors
SATCOM AirCell Iridium**

Exterior: Base Paint: Snow White / Stripe Colors: Gray, Light Blue and Black

**Interior Configuration: Number of Seats 13 Galley Configuration Forward
Lavatory Configuration Forward and Aft**

Interior

**Galley Location: Forward
FWD Cabin Configuration Four (4) Place Club w/Foldout Tables
MID Cabin Configuration Four (4) Place Conference Group w/ Credenza
AFT Cabin Configuration: Divan Opposite 2-Place Club
Lavatory Locations: Forward and Aft
Galley Equipment: Microwave Oven; Convection Oven; Coffeemaker
Other Notable Features: Sleeping accommodations for 5-7 Passengers; VIP Panel for Second Aft Seat; VIP Panel and SVGA Port at VIP Seat; Interior Soft Goods
august 2016**

These specifications have been prepared and are intended as a general guide to the aircraft. Luxury Jet cannot, however, be liable for any inaccuracy. It is up to the purchaser to confirm details of concern by survey, inspection and/or inquiry of the seller and to ensure that the purchase contract properly reflects client's concern and specific details upon which they may rely. Luxury Jet Aviation LLC always advises an independent survey to be performed on behalf of the Purchaser